St Lawrence Chapel Warminster East Window Repairs May to August 2023











Salisbury Cathedral Stained Glass
The Cathedral, Salisbury, Wiltshire, SP1 2EN
glass@salcath.co.uk
Accredited to ICON
www.salisburycathedral.org.uk



Our Ref SK1336
St Lawrence Chapel
c/o Mr Ian Frostick
High Street
Warminster
Wiltshire
Dear Mr Frostick

20th September 2022

Re: St Lawrence Chapel, Warminster

With reference to our site meeting, we would submit our estimate as follows.

East Window

A 19th century (1855) stained glass window comprising of 3 no main lights 3 no tracery panels and 4 no squints. The window depicts, St Stephen, Christ in Glory and St Lawrence, set within canopy work. The maker of this window is not as yet known.

The glazing of this window is found in a generally very poor condition, the lead work being very weak, coupled with loss of ties on the saddle bars. This has become known following recent works to carry out insitu repairs to a small number of broken sections of stained glass. Considerable care was required to ensure that the glazing was not pushed apart while this work was being carried out.

The condition of the painted detail would appear to be reasonable, but this will need to be assessed on the bench prior to any works being carried out, to ensure there is no loss of detail during the restoration process.

There are wire guards as external protection on all of the lights.

This window being positioned on the East Elevation directly adjacent to another building has offered it protection from high winds, but its condition is now such that poor weather is likely to bring about a failure in the lead matrix.

We would suggest that this glazing be removed for re-leading as soon as is practical.

To travel to site and remove 3 no main lights, 3 no tracery panels and 4 no squints from the stonework and temporary glaze with ply boarding.

Return the lights to the workshop, photograph on the light box, take rubbings and mark with CVMA notations.

Strip the glass from the old lead work and re-lead in a new lead calm of the same visible profile as the original. Cracked sections of glass to be edge bonded with a combination of, Silcoset 153, Araldite 20/20 or copper foil strapping, whichever is most appropriate in each case.

The completed lights to be waterproofed using traditional lead light cement. If it is found that the paintwork condition gives cause for concern, the internal surface of the lights to be carefully cemented by hand to ensure no loss of painted detail.

New copper wire ties soldered to the lead work joints to allow fixing to the internal saddle bars.

All to be photographed on the light box prior to re-installation.


All to be returned to site and fixed back into the stonework and finished with a lime based mortar, incorporating new non-ferrous saddle bars painted black.

The external wire guards to be re-instated.

The above for the sum of £11,315.00 excluding VAT

If a conservation report is required there will be an addition to the above cost of

£368.00 excluding VAT, as this will require a further visit to site to provide the photographs needed to prepare the report and provide additional information.





Salisbury Cathedral Enterprises Ltd. Registered in England no:556116 VAT no: 474461024 Registered Office: The Chapter Office, 6 The Close, Salisbury, Wiltshire, SP1 2EF

Tracery Stonework

It has been noted that some of the stonework joints within the tracery of the window would benefit from being pinned to ensure that they remain in position.



We would offer a cost of £317.00 excluding VAT to pin the six joints that have been identified, using stainless steel pins and stone epoxy resin to ensure there is no slipping of the joint. The joints to be finished with a lime based mortar to prevent water ingress.

Note: This work will require a portable tower scaffolding internally and externally while removal and re-instatement works are taking place, internally this may be in place for three days. Externally it will be removed at the end of each working day.

Public access to the window area will be restricted while the works are in progress.

All of the above costs are exclusive of VAT and are based on today's rates for labour and materials. Your attention is drawn to our standard terms and conditions enclosed.

Please contact me if we can be of further assistance.

Yours sincerely

S Kelly

S Kelly ACR AMGP
Manager/Senior Conservator

Glass Paint Deterioration

One of the issues with stained glass of any period can be the deterioration/loss of painted detail from the glass surface. This is most common in 19th century glass but can be found in earlier glass as well and is always an issue that is foremost in the conservator/restorers mind when first assessing a window's condition.

The glass paint in general terms is a ferrous oxide/finely ground glass compound, in the form of a very fine powder. This product can be mixed with almost any medium that will dry onto the glass surface, these are most commonly: water/turps/ascetic acid/lavender oil etc. These allow the powder medium to be applied to the glass with a brush and then dry on to the surface of the glass.

Once the glass paint is on the glass surface it must then be fired in the kiln to make the paint permanent on the glass surface. For this to be carried out correctly and depending on the requirements of the glass paint used, a temperature of between 650-690c must be attained. At these temperatures the glass surface is just becoming molten and the glass paint will fuse with the molten glass surface.

If the correct temperature is not reached the paint cannot fuse with the glass surface and remains on the surface, in a condition that renders it susceptible to deterioration in the presence of moisture (water soluble).



19th century glass



16th century glass

Over time if this glass is in a situation where condensation is an issue, the continuous wetting and drying cycles will slowly remove the painted detail from the glass and at its worst leave no artwork on the glass at all.

It is also possible that 'Borax' has been added to the paint mix before firing. The addition of this material has the effect of appearing to lower the temperature that is required to fire the paint onto the glass surface. Unfortunately what has taken place in the kiln is the Borax has formed a very hard layer on the top of the paint, so that it appears to be fired, but in fact is still under-fired and water soluble.

Little can be done to stop the deterioration of the painted surface if left in a situation where moisture is present, so it is very important to stop or at least limit the amount of time that moisture is on the glass surface.

This can be achieved in various ways, with varying degrees of success, but in general terms in ancient buildings a sympathetic heating system coupled with good ventilation can bring about a marked improvement in controlling moisture within a building.

To introduce air flow over the internal surface of the window by the introduction of low wattage heaters at sill level to cause a rising flow of air travelling up the window can also have the desired effect in some instances.

To introduce a system of vented secondary glazing to the external surface of the glass, is the most effective method of preventing moisture on the internal glass surface and at the same time providing protection for the external surface. There are however, a greater number of issues to be overcome when introducing this method as it will always alter the external view of the window to varying degrees and may also have the same effect internally

Wherever the loss of glass paint is an issue it will always require discussion between Glass Conservator, Architect, Church, Conservation Bodies etc to agree the best course of action in each individual case.

© Salisbury Cathedral Stained Glass 2011

Minutes of the Meeting of Warminster Town Council on Monday 28 th November 2022 at 7pm held at the Civic Centre, Sambourne Road, Warminster, BA12 8LB

Membership:

Clir Allensby (West)	*	Cllr Keeble (West) Vice Chairman of the Council and Deputy Mayor	*
Cllr Brett (East)	*	Cllr Macdonald (East)	Α
Cllr Cooper (Broadway)	Α	Cllr Macfarlane (West)	*
Cllr Davis (East)	*	Clir Parks (North)	*
Cllr Fraser (West)	*	Cllr Robbins (East) Chairman of the Council and Mayor	*
Cllr Fryer (Broadway)	*	Cllr Syme (Broadway)	Α
Cllr Jeffries (North)	*		

Key: * Present A Apologies AB Absent

Member resolved to award £24,600 to the repairs with an additional £5,400 available as a contingency. Funding to be allocated from the Community Infrastructure Levy.

Salisbury Cathedral Stained Glass

Finance Department, The Chapter Office, 6 The Close, Salisbury, Wilts, SP1 2EF
Tel. 01722 555132 Email: finance@salcath.co.uk

VAT Number GB 474 4610 42



Invoice

To:		Delivery Address:		
St Lawrence Chapel, Warminster		St Lawrence Chapel, Warminster		
c/o Heather Parks		c/o Heather Parks		
2B Prestbury Drive		2B Prestbury Drive		
Warminster		Warminster		
BA12 9LB		BA12 9LB		
Customer Ref:	Account No:	Invoice No:	Date:	
K2218	00000518	0000114828	08/08/2023	

Description	Quantity	Unit Value	Net	VAT	Gross
St Lawrence Chapel, Warminster					
East Window Restoration As per our estimate dated 20th September 2022	1	11315.00	11,315.00	2,263.00	13,578.00
Plus, extra to pin stonework joints within the tracery	1	317.00	317.00	63.40	380.40

BACS Payment : Lloyds Bank Salisbury Sort Code 30-97-41 Account No. 00360700 Salisbury Cathedral Enterprises Ltd SWIFT/BIC: LOYDGB21063 IBAN: GB 40LOYD 30974100360700

Please make cheques payable to Salisbury Cathedral Enterprises Ltd				
VAT Analysis				
Code %	Net VAT			
1 20.00 T- standard rate	11632.00 2326.40	Net Total	11632.00	
0.00	0.00	VAT	2326.40	
Terms 30 days from documen	nt date	Total Due	£13958.40	

Warminster, St Lawrence Chapel

East Window, Pre-restoration

A 19th century (1855) stained glass window comprising of 3 no main lights 3 no tracery panels and 4 no squints. The window depicts, St Stephen, Christ in Glory and St Lawrence, set within canopy work. The maker of this window is not as yet known.





The glazing of this window is found in a generally very poor condition, the lead work being very weak, coupled with loss of ties on the saddle bars. This has become known following recent works to carry out insitu repairs to a small number of broken sections of stained glass. Considerable care was required to ensure that the glazing was not pushed apart while this work was being carried out.

Removal of this glazing for re-leading should be considered as a priority, to ensure the security of this window.

Post Restoration

All glazing panels were removed <u>from the stonework</u>, to the workshop. Rubbings of each panel taken and marked with CVMA <u>notations</u>, photographs of each panel taken on the light box prior to de-glazing. Wire guards take down and put aside for later re-instatement.





Removal of the glazing from the stonework



Taking rubbing of the panels prior to de-glazing

There is some movement in the tracery stonework that will require pinning to stabilise.

It was noted on removal that there were insufficient support bars to the figurative elements, these would appear to have been removed at some point and coper ties cut off. This is one of the factors that has contributed to the general condition of the glazing, allowing more movement to take place in these areas, the lead work to the figures being weakened to the point, that strong wind or a light impact could easily have resulted in the glazing failing.



Bars have been removed from the figures

The glass was found to be in a well fired stable condition, with only the leadwork being of real concern. The artist responsible for this window has not been identified, but close inspection of the painted detail reveals someone of considerable talent, especially in the areas of grisaille detail that forms the background to the figures.





Fine qualities of painted detail

The glass has been cleaned with de-ionised water to remove general dirt and grime from the surface and a small number of historic breakages have been edge bonded. Some daylight border sections have been replaced, mostly to the tracery panels following breakages on remove, due to the panels being slightly off the stonework shape with some daylight borders set in the mortar.


All the lights have been re-leaded in a new lead calm of the same visible profile as the original, the completed lights being waterproofed with traditional lead light cement and new copper wire ties soldered to the internal lead work joint to allow fixing to the saddle bars.





Re-leading on the original glass on the bench








Waterproofing the glazing, application, drying, picking to remove the excess



New copper ties solder to lead work joints.

Extra bars have been provided in those areas on the figurative element, where they had previously been removed.




Introduction of two extra bars for each figure, to ensure proper support.

The completed panels were photographed on the light box, prior to installation.

All was returned to the church and fixed back into the stonework and finished with a lime-based mortar, incorporating new non-ferrous saddle bars painted black.



Finishing the internal fixing of the glazing



Completed window.



Those areas of movement in the tracery stonework were drilled and pinned using non-ferrous bar, to stabilise.

External wire guards were re-instated and fixed with non-ferrous plug and screw fixings.







Warminster Before LIH

Warminster Before Centre


Warminster Before RIH



























































































PAGE 16 FRIDAY, 16th JUNE, 2023 THE WARMINSTER JOURNAL



Nesting Time

The Editor, Warminster Journal

The Editor Warminster Journal
Dear Str.
Please Could we remind
Journal readers and keep and model/pithed to efficially open
these must the RSPB and
other widtle lovers recommend avoiding hedge cutting
during the main broeding as best and it means
and maintenance of the second and the second

someone is cutting a pe during this period. ik to them and politely tion the risk to birds' i, and the laws protecting

they proceed, and you there is an active nest at contact the police and or a reference number.

Yours sincerely e and address supplied

Photo Contributions

n in the Journal, but please nd them as an attachment, jpg or tif, and not bedded within a Word file. all messages must be no per than 5Mb.

Warminster and West-Journal and Wits County liser typeset and pub-by Coates & Parker Ltd. ectors and editors R. C. and Mrs. D. J. Watkins horto) at their registere 35 Market Place, War , fax 01985 217680.

coatesandparker.co.uk coatesandparker.co.uk ne copyright of Coates &

AY, 16th JUNE, 2023

Serving Up A Slice Of Summer

The newly revamped tennis courts in the Lake Pleasure Grounds were officially opened by the mayor on Wednesday ready for an ace time for summer.

summer.

The courts have been in rest was contributed by the seemarked seemand an explanation of the decoack has been over reserves.

The courts have been in rest was contributed by the seemand an explanation of the property of the process to assess the left process the left proc

and declares the revamped facilities fully open.

Delivering a brighter, greener future for all

A special celebratory cake marked the occasion

AESEOTPE NZZI

REMINDER

letters to the editor should be a maximum of 250 words. They

must be signed and give a home address (even if it is not

wholimingly positive, according to the town council.

Cutting the ribbon. Warminarea (MUSA) for public piley, policy piley, po

their details, it was fascinating to see the care, skill and
quality of the repairs."
Selfsbury Cathedral Class
is on track to reinstall the
widows Mid-July. The Team
has been taking photographs
throughout the process to risure a permanent record is vallable for the Chapel, the County Listed Building department and for the National Stained Glass Archive.

lan Frostick added, 'The eoffees and Trustees would like to express their gratitude to Warminster Town Council for the Community Infrastructure Levy grant to support these essential repairs. Warminster mayor Phil Keeble cuts the ribbon Judith will update the counciliors and wider team on the dows. progress of the work.



Specialist Work On

Windows Underway

Piecing together history



The delicate process to repair the historic win-



The restoration work is making good progress

Copyright Warminster Journal

Archdeacon Alan Jeans Blesses St. Lawrence **Chapel Projects**

The Feoffees and Trustees of St. Lawrence Chapel were extremely pleased to welcome Archdeacon Alan Jeans to officiate at their Patronal Service on Sunday, celebrating the life of St. Lawrence.

One hundred and sixty. The clock and bell mecha-years later the stained-glass nisms were disconnected to panels were carefully prevent damage and carefully removed, extensive repairs moved to allow the essential undertaken and have now repair work to the clock room been reinstalled after three foor. Everything is now back morths of expert work by the in place and recommissioning Salisbury Cathedral Glass work is being undertaken by team.

the windows on behalf of the tember. Current Bishop of Salisbury.

Other Rems also blessed com's visit, the flower team included: the new Patronal arranged displays throughout lectern fall made by Chapol the Chapel. Trustee Lesley Fudge, the Also on show were descriptomyleted repairs by F. Stons and photographs of the Worldong's carpenters to the various projects. tower clock room floor and the The Feoffees would like Moulding's stone masons, port the various surveys, plan-these were highlighted by ning approvals, window and structural engineer Andrew tower repairs. structural engineer Andrew tower repairs.

Waring as a longer-term risk. To estibilitate the completion to the tower stability; the completion of the Queen Elizabeth tage fours will be available in
if Platinum Jubilee Memorial September. This will include
Garden, including two new trips up the tower to see the
benches, these works were clock and bell reports. No

In 1857, after several years brother Roderick; extensive of closure due to estimate repairs and servicing of the building work, the Bishop of Chaper's Grain et Tisted Scussibury reconsocrated the damore organ undertaken by Chapel. This included the Organ Design (Alton) and recently installed east win-financed by the Friends of the

Feofice Dan Neeme. The Archdeacon, supported by Rev. Susan Feeter blessed bells chiming again in Septite windows on behalf of the tember.

panelled celling after three of express their graftude to War-the original 13th century minister Town Council for the beams failed, the Silling in of Community Infrastructure 39 historic beam holes by F. Grant. This was used to sup-

supported by the Friends of bookings required just poin, the Chapet, the Feoflees' writes lan Frostick, chairman Trustees, Wattrose, bequiests of the Feoflees and Trustees, from Stephen Pearson, Mar- St. Lawrence Chapet.



Archdeacon Alan Jeans blesses the window



A lovely floral display by the Chapel floral team to celebrate the Archdeacon's visit.



Information about the Chapel of St. Lawrence is A further blessing on all the work recently done on Display.



Archdeacon Alan Jeans officiates at the Patronal Service on Sunday, celebrating the life of St.



The Rev. Susan Foster is involved in the blessing of the new Patronal lectern fall made by Chapel Trustee Lesley Fudge.



Copyright Warminster Journal

