

Paneled Ceiling Repairs



The failure of the Clock room beams caused the attached panel ceiling to drop.

Initially we arrange for support props to limit further damage. Once the new beams were installed the Clock Room floor was lifted back into place.

The panelled ceiling was reattached by Moulding's carpenters. This included repairs to broken wooden boxing and the replacement of several beading strips.

These essential repair work was supported by the Warminster Town Council with a Community Infrastructure Levy (CIL) grant.

Paneled Ceiling Repairs



MOULDING

CELEBRATING
225 YEARS
1798 - 2023

Paneled Ceiling Repairs



MOULDING

CELEBRATING
225 YEARS
1798 - 2023

Paneled Ceiling Repairs



MOULDING

CELEBRATING
225 YEARS
1798 - 2023

Paneled Ceiling Repairs



MOULDING

CELEBRATING
225 YEARS
1798 - 2023