

The Chapel Of St. Lawrence Stained Glass Window Returns

The main east stained glass window panels have been reinstalled after almost three months of careful repair by Sam Kelly and the expert team at Salisbury Cathedral Glass.

The windows were originally installed in 1855. The lead work had started to fail after 168 years and damage to the historic glass was evident. Upon inspection it was recommended that the windows were urgently removed for repair. This involved careful removal of the glass, complete disassembly, cleaning, glass repairs, new lead work and weather proofing.

The windows have now been reinstalled and additional repairs made to the stonework arches. The Feoffees and Trustees are grateful to Warminster Town Council for the award of a CIL (Community Infrastructure Levy) Grant to undertake these vital repairs. Writes Ian Frostick (Chairman of the Feoffees and Trustees St Lawrence Chapel).



Work progresses on the outside on Tuesday of last week.



The team are hard at work



Ongoing work on the inside on the morning of Wednesday of last week



A section from the stained glass window showing our Lord and saviour, Jesus Christ.



Work on the outside was completed on Wednesday of last week.



Completed on the Wednesday afternoon – unfortunately the leaden sky with heavy rain meant not much light was shining through!